

These the most important type. They are mostly used in corrosive systems, especially in acidic and high temperature condition . The main application of ceramic packing ; as filling tanks/towers packing and Absorption towers, distillation of Oil , Gas , Petrochemical units as well as it is widely used in the chemical industry.

Ceramic packing has different sizes and shapes , includes Raschig Ring , saddle , pall Ring , Honey Comb , Cross Ring , Penta Ring , and ...

Carbonic packing is another type which can be used in hot alkaline , acidic and non-oxidizing condition.

This type can be produced in Raschig Ring form and different sizes.